



# Site Meeting Notes

**Meeting Date:** 12/14/17

**Subject:** Trabuco Mesa ES Meeting Notes

**Meeting Location:** Trabuco Mesa ES

**Project:** SVUSD Facilities Master Plan 2019

**PBK Project No.:** 17331

## Site:

- Exterior lighting is not sufficient for events.
- Gates throughout campus do not close adequately
- HVAC making rooms too humid
- Wood doors need to be replaced campus-wide
- Uneven concrete is creating trip hazards
- Railroad ties need replacement
- Block wall on Antonio Parkway needs repairing
- Flooring tile at SAI portables need to be replaced
- Access to HVAC units at portables is challenging
- Exterior concrete walkways are slippery
- Play structure needs to be repaired/replaced
- New landscaping needed around play structure
- Lunch shade structure is too small
- Turf grass area is not big enough
- Play area is too small
- Artificial turf needs replacement
- Need rubberized play surface
- Shade at tables between lunch area and MPR is needed

## Next Generation Classroom:

- Classrooms don't have enough tack-able walls
- Electrical in classrooms need to be upgraded to meet new technological demands
- Admin needs more tack-able surface

## Technology:

- Smart boards and projectors need to be upgraded
- Sound system in MPR needs to be repaired or replaced

## Support Space:

- MPR needs A/V and sound system
- More cabinet space needed in the Health office